

US EPA ARCHIVE DOCUMENT

UNIT LOG	1. Incident Name Kalamazoo River/Enbridge Oil Spill	2. Date Prepared 09/07/2012	3. Time Prepared 1600
4. Unit Name/Designators Situation Unit	5. Unit Leader (Name and Position) Isaac Aboulafia, Planning Section Chief		6. Operational Period 0700, 09/6/12 – 0700, 09/13/12
7. Personnel Roster Assigned			
	Name	ICS Position	Home Base
	Larry Rader	Situation Unit Leader	Chicago, Illinois
8. Activity Log			
Time	Major Events		
0940	<p>Boat safety briefing at C0.4 boat launch. Launch.</p> <p>Operational status:</p> <ul style="list-style-type: none"> • Observed sheen and tar globules along LDB across from C0.4 boat launch. • Observed sheen and tar globules in river channel near trestle at MP 5.75. • Observed sheen and tar globules within containment at control point above Ceresco Dam. • Observed crew removing debris from control point above Ceresco Dam. • Observed sediment trap at MP 10.75 LDB, sheen observed behind sediment trap. Crew removed sorbent boom along shore behind containment boom. • Observed poling crew operating at MP 33.0A RDB. • Observed rainbow sheen and strong petroleum odor at MP 33.1 RDB. • Observed crews removing debris from boom configuration C in Morrow Lake Delta and E4.0 containment boom. • Observed inspection crew inspecting boom in Morrow Lake Delta along boom configuration C. • Observed Morrow Lake Delta monitoring crew conducting poling in river channel in Morrow Lake Delta. • Observed sheen sweeper boat operating in central channel of Morrow Lake. • Observed sheen and tar globules in north and south coves on Morrow Lake. 		
	Additional observations: None		
1430	Complete ground survey at E4.0 boat launch, return to ICP.		
9. Prepared by (Name and Position) Larry Rader, Situation Unit Leader, USEPA-START			